

# SONY car stereo

## Service Bulletin No.88

Technical Department  
Sony Service Company  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-530R

Date: October 16, 1987

Subject: Missing Part Number For  
Variable Resistor

**Symptom:**  
(\*\*)

The part number for the variable resistor RV102, 202 (VOL), RV303 (BAL), RV103, 203 (FADER) is not listed in the service manual. Please add the part number to your service manual on page 64.

**Solution:**

Ref. No.	Description	Part Number
RV102, 202	Volume	1-237-217-11
RV303	Balance	
RV103, 203	Fader	