

SONY.

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-5

No. 94

Subject: Part Number Missing - Transit
Screw

Date: March 11, 1988

Symptom:
(**)

The transit screw is not shown in the service manual nor listed in the parts list. The part number is shown below.

Solution:

Description	Part Number
Transit Screw	3-323-254-01
Transit Screw Caution Label	3-323-248-01

Compact Disc

CSA-14

Reference:

PRINTED IN U.S.A.
CSA-14288-1