

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-7300/7100, CDX-R88

No. 97R

Subject: Improvement Of Tuner Performance **Date:** January 2, 1989

Symptom:
(21)

Customer complains of sensitivity or adjacent stations bleeding through.

Solution: Please change the ceramic filters CF1 and CF2.

Ref No.	Description	Former	New
CF1, CF2	Ceramic Filters	1-527-344-91	1-567-415-11

CSA-14 Tuner/Tape Deck/Compact Disc

Reference: Fax #A880301 March 16, 1988

PRINTED IN U.S.A.
CSA-141288-1