

SONY.

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-747R

No. 101

Subject: Missing Part Number In
Service Manual


Date: May 9, 1988

Symptom:
(**)

The part number for resistor R560 was omitted in the Service Manual.

Solution: Please add the part number given below to your Service Manual:

Ref No.	Description	Part Number
R560	22 Ohm 1/6W Carbon Res.	1-247-791-00



R560

Reference:

PRINTED IN U.S.A.
CSA-14488-6

CSA-14 Tuner/Tape Deck