

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-75/85

No. 102

Subject: Selection Of Replacement Tape
Head


Date: May 23, 1988

Symptom:
(**)

There are two different tape heads available for the XR-75 and the XR-85, because their mounting brackets are shaped differently.

Solution: Please identify the head type before ordering.

Ref No.	Description	Part Number	
		Former	New
XR-75/85	PB Head	1-543-181-00	1-543-181-12



-00



-12

Receiver/Cassette

CSA-14

Reference: T/N A0004

PRINTED IN U.S.A.
CSA-14488-7