

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: RM-X2

No. 105

Subject: Missing Part Number - IC305

Date: July 29, 1988

Symptom:
(**)

The part number for IC305 is missing in the service manual.

Solution: Please add this part number to your service manual:

Ref No.	Description	Part Number
IC305	MPD75106G-532	8-759-142-02

Compact Disc
CSA-14

Reference: FAX A880619

PRINTED IN U.S.A.
CSA-14788-2