

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-75/85/100

No. 111

Subject: Reference Number Correction -
Wheel Worm Assembly


Date: October 10, 1988

Symptom:
(**)

Please note the reference number correction for the worm wheel assembly of service manual supplement #1.

Solution: Please add the correct reference number to your manual.

Reference Number		Description	Part Number
Incorrect	Correct		
320	326	Wheel Ass'y Worm	3-592-626-00



CSA-14 Tuner/Tape Deck

Reference: FPR Audio 000433

PRINTED IN U.S.A.
CSA-141088-1