

SONY

Car Stereo
Service Bulletin

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-5000

No. 118R1

Subject: Missing Part Number

Date: July 13, 1990

This Service Bulletin Supersedes Service Bulletin No. 118.

Symptom:
(**)

The part number for the wiring harness is not listed in the service manual.

Solution:

Please add the following part number to your service manual:

Description	Part Number
Cord With Connector	1-575-911-11

Tuner/Tape Deck
CSA-14

Reference: Fax #A881422

PRINTED IN U.S.A.
CSA-14690-1