

SONY.

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XS-PL55

No. 122

Subject: Part Number Error in Service Manual **Date:** February 23, 1989

Symptom:
(**)

The tweeter part number in the service manual is incorrect.
The descriptions are also reversed.

Solution: Please correct your service manual as shown below:

Description	Part Number	
	Former	New
Woofers	1-544-010-11	1-503-989-11
Tweeters	1-503-989-11	1-503-990-11

CSA-14 Speakers

Reference: KCP

PRINTED IN U.S.A.
CSA-14189-2