

**SONY**

**Car Stereo  
Service Bulletin**

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive Park Ridge, New Jersey 07656

**Model:** XK-8D

**No.** 127

**Subject:** Reference Numbers Are Reversed


**Date:** May 8, 1989

**Symptom:**  
(\*\*)

The reference numbers for the phono cord and the power cord are reversed.

**Solution:** Please correct your service manual as shown below:

Ref. No.	Description	Part Number
912	Power Cord	1-559-424-11
913	Phono Cord	1-559-539-11



Reference:

PRINTED IN U.S.A.  
CSA-14489-3

Tape Deck  
CSA-14