

**SONY**

Car Stereo  
Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** XR-7100

**No. 139**

**Subject:** Reference Numbers Are Reversed

**Date:** May 24, 1989


**Symptom:**  
(\*\*)

Reference Numbers 6 and 20 are reversed in the service manual.

**Solution:**

Please correct your service manual with the correct numbers shown below:

Ref. No.	Description	Part Number
6	LCD Glass Window	3-332-135-01
20	Auxiliary Indicator Plate	3-332-166-01



CSA-14 Tuner/Tape Deck

Reference: KCP

PRINTED IN U.S.A.  
CSA-14589-6