

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-R79

No. 154

Subject: Part Number For IC501

Date: February 2, 1990

Symptom:
(**)

The part number for IC501 is incorrect on page 47 of the service manual.

Solution: Please correct your service manual with the part number listed below:

Ref. No.	Description	Part Number	
		Incorrect	Correct
IC501	CXP5048H-188Q	8-752-806-04	8-752-80 <u>9-49</u>

Compact Disc
CSA-14