

**SONY**

Car Stereo  
Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

---

**Model:** XM-3520, XM-3040

**No. 155**

**Subject:** Units Stay In Protect

**Date:** February 2, 1990

**Symptom:**  
(12)

When the unit is connected on a test bench or in a dealer display panel, the unit will stay in the protect mode.

**Solution:** Signal ground and battery ground are separate in these units. These grounds will be connected through the car stereo when its Line Out is connected to the Line In of the XM. If Signal In is removed, the unit will go to protect.

CSA-14 Amplifier

---

**Reference:**

PRINTED IN U.S.A.  
CSA-14190-3