

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-7050

No. 156

Subject: Part Number For Transistors

Date: February 2, 1990

Symptom:
(**)

The part numbers for transistors Q461 and Q471 are listed incorrectly on page 28 of the service manual.

Solution: Please correct your service manual with the part numbers listed below:

Ref. No.	Incorrect		Correct	
	Description	Part Number	Description	Part Number
Q461, Q471	2SC3900	8-729-805-40	DTC143TF	8-729-900-46

CSA-14 Tuner / Tape Deck