

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-A2001

No. 159

Subject: Wrong Part Number For KSS Assembly **Date:** February 16, 1990

Symptom:
(**)

The part number for the optical assembly is wrong in the service manual.

Solution: Please note the correct part number listed below in your service manual:

Description	Part Number	
	Incorrect	Correct
KSS Assembly	8-729-146-11	8- 848 -146-11

Compact Disc

CSA-14