

**SONY**

Car Stereo  
Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** XR-550R

**No. 160**

**Subject:** Part Number Missing - Remote Scan  
Switch (S-601)

**Date:** February 16, 1990

**Symptom:**  
(\*\*)

The part number for the Remote Scan Switch (S-601) is not listed in the service manual.

**Solution:** Please add the following part number to your service manual:

Description	Part Number
Remote Scan Switch (S-601)	1-463-735-11

CSA-14 Tuner / Tape Deck

Reference:

PRINTED IN U.S.A.  
CSA-14190-8