

SONY

Car Stereo
Service Bulletin

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XM-3060, XM-5520, XM-5540

No. 169

Subject: Part Number For Level Adjustment Control

Date: May 16, 1990

Symptom:
(**)

The part numbers listed in the service manual for the Level Adjustment Control are wrong. The part listed is a right angle mount, while the part actually used is a vertical mount.

Solution: Please correct your service manual as listed below:

Model	Ref. No.	Part Number	
		Incorrect	Correct
XM-3060	RV601-603	1-238-826-11	1-238-880-11
XM-5520	RV601	1-238-826-11	1-238-880-11
XM-5540	RV601-602	1-238-826-11	1-238-880-11

CSA-14 Amplifier