

SONY

**Car Stereo
Service Bulletin**

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey, 07656

Model: XR-5500

No. 176

Subject: Missing Part Number For PM-900


Date: October 15, 1990

Symptom:
(**)

The Plunger Solenoid shown on page 13 as PM-900 does not have a part number listed. The same solenoid is shown on page 15 as PM1. PM1 should actually be PM-900.

Solution: Please correct the Reference and Part Number for PM-900 as follows:

Ref. No.	Description	Part Number
PM-900	Solenoid	1-454-464-11



CSA-14 Radio/Cassette