

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: GENERAL-CAR

No. 193

Subject: New Error Disc Available - YEDS-41 **Date:** February 8, 1991

Symptom:
(**)

There is a new error disc available. It has Black Dot, Red, Dot, and Fingerprint errors on the disc. The maximum dot error size is 1.1mm.

Solution: This disc should be ordered for evaluating tracking performance of CD Players. The part number is listed below:

Description	Part Number
YEDS-41 Error Disc	3-702-529-01

Compact Disc

CSA-14