

SONY

Car Stereo
Service Bulletin

Sony Service Company : Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CPM-200/-200P/-200A

No. 196


Subject: Availability Of Replacement Parts **Date:** April 15, 1991

Symptom:
(**)

The Flexible Pipe Assembly and Base replacement parts are now available.

Solution: Please update your service manual with the part information listed below:

Ref. No.	Description	Part Number
A	Flexible Pipe Assembly	X-2120-510-1
B	Base	2-120-542-01



CSA-14 Miscellaneous