

Car Stereo Service Bulletin

CSA-14

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: XTC-100

No. 356

Subject: Part Description And Part Number Correction: Q529. **Date:** March 17, 1995

Symptom:

(**)

The description and part number shown in the service manual for Q529 is incorrect.

Solution: Please correct your service manual as follows:

REF	DESCRIPTION		PART NUMBER	
	INCORRECT	CORRECT	INCORRECT	CORRECT
Q529	TRANSISTOR, 2SD1664-QR	8-729-920-85	TRANSISTOR, 2SC1623-L5L6	8-729-120-28



Filename: CAR0356.SB
Directory: J:\SBDOC\MAR95
Template: C:\WINWORD\S_BULL.DOT
Title:
Subject:
Author: Hoyt Wing Lee
Keywords:
Comments:
Creation Date: 03/17/95 4:01 PM
Revision Number: 2
Last Saved On: 03/17/95 4:01 PM
Last Saved By: Hoyt Wing Lee
Total Editing Time: 0 Minutes
Last Printed On: 04/01/96 9:30 AM
As of Last Complete Printing
Number of Pages: 2
Number of Words: 121 (approx.)
Number of Characters: 695 (approx.)