

Car Stereo Service Bulletin

CSA-14

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-5070/5270/5470/5490

No. 362

Subject: Part Number Addition: Tuner Pack (FE601).


Date: May 1, 1995

Symptom:

(**) The part number for the tuner pack, ref. FE601, is not listed in the service manual.

Solution: Order the tuner pack as shown below.

REF	DESCRIPTION	PART NUMBER
FE601	TUNER PACK, TUX-001A	A-3282-003-A



Filename: CAR0362.SB
Directory: J:\SBDOC\MAY95
Template: C:\WINWORD\S_BULL.DOT
Title:
Subject:
Author: Hoyt Wing Lee
Keywords:
Comments:
Creation Date: 05/01/95 10:42 AM
Revision Number: 2
Last Saved On: 05/01/95 10:42 AM
Last Saved By: Hoyt Wing Lee
Total Editing Time: 0 Minutes
Last Printed On: 04/01/96 9:39 AM
As of Last Complete Printing
Number of Pages: 2
Number of Words: 110 (approx.)
Number of Characters: 628 (approx.)