

Car Stereo Service Bulletin

CSA-14

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-5290

No. 379

Subject: Part Number Correction - Reference No.
LCD801, Display Panel, Liquid Crystal

Date: October 26, 1995

Symptom:


(**)

The part number listed on page 42 of the Service Manual for Ref # LCD801, Display Panel, Liquid Crystal, is incorrect.

Solution:

Please note the correct part number as shown below.

REF	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
LCD801	DISPLAY PANEL, LIQUID CRYSTAL	8-759-289-80	1-810-847-21



Filename: CAR0379.SB
Directory: J:\SBDOC\OCT95
Template: C:\WINWORD\TEMPLATE\S_BULL.DOT
Title:
Subject:
Author: Hoyt Wing Lee
Keywords:
Comments:
Creation Date: 10/26/95 10:51 AM
Revision Number: 2
Last Saved On: 10/26/95 10:51 AM
Last Saved By: Hoyt Wing Lee
Total Editing Time: 0 Minutes
Last Printed On: 04/01/96 10:40 AM
As of Last Complete Printing
Number of Pages: 1
Number of Words: 125 (approx.)
Number of Characters: 713 (approx.)