

Car Stereo Service Bulletin

CSA-14

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-T60

No. 387

Subject: Description & Part Number Correction -
Reference No. D601, LED, DSA3A4

Date: December 14, 1995

Symptom:

(**)

The description and part number listed on page 39 of the Service Manual for Ref # D601, LED, DSA3A4, is incorrect.

Solution:

Please note the correct description and part number as shown below.

REF	DESCRIPTION		PART NUMBER	
	INCORRECT	CORRECT	INCORRECT	CORRECT
D601	LED, DSA3A4	LED, EL308	8-719-945-59	8-719-029-26

