

# Car Stereo Service Bulletin

**CSA-14**

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

---

**Model:** MDX-400

**No.** 391

**Subject:** Finish Wears Off Of Buttons.

**Date:** March 25, 1996

**Symptom:**  
(14)

The finish may wear off of the surface of the buttons.

**Solution:**

If the finish wears off of any of the buttons, replace all of the buttons with those included in the parts kit shown below.

REF	DESCRIPTION	PART NUMBER
-	BUTTON ASSEMBLY	X-3372-036-1

Applicable serial numbers: up to 21232



Filename: CAR0391.SB  
Directory: J:\SBDOC\MAR96  
Template: C:\WINWORD\TEMPLATE\S\_BULL.DOT  
Title:  
Subject:  
Author: Hoyt Wing Lee  
Keywords:  
Comments:  
Creation Date: 03/25/96 10:34 AM  
Revision Number: 2  
Last Saved On: 03/25/96 10:34 AM  
Last Saved By: Hoyt Wing Lee  
Total Editing Time: 0 Minutes  
Last Printed On: 04/01/96 9:37 AM  
As of Last Complete Printing  
Number of Pages: 1  
Number of Words: 118 (approx.)  
Number of Characters: 675 (approx.)