

CONFIDENTIAL

CSA-14

Sony Service Company
National Technical Services
A Division of Sony Electronics Inc.
Park Ridge, New Jersey 07656

Service Bulletin Car Stereo

Model: CDX-91

No. 402

Subject: RESET INDICATED OR ONE DISC LEFT IN MECHANISM.

Date: July 25, 1996

Symptom:

(62)

The unit may reset or one CD may be left in the mechanism.

Solution:

Apply a piece of filament tape to the Case (Lower). This will protect the Case (Lower) and Flexible board from touching each other.

Applicable Serial Numbers: up to 29900

