

**Model:** XM-2040**No.** 426**Subject:** THE CAR BATTERY MAY GO DEAD**Date:** May 6, 1997**Symptom:****(111)** The Car battery may go dead with audio systems using the XM-2040.**Solution:**

The value of R913 is incorrect. Change R913 to the new part listed in the table below. The resistor is on Amplifier (A) Board.

| REF  | FORMER          |              | NEW              |              |
|------|-----------------|--------------|------------------|--------------|
|      | DESCRIPTION     | PART NUMBER  | DESCRIPTION      | PART NUMBER  |
| R913 | 1K OHM RESISTOR | 1-249-417-11 | 22K OHM RESISTOR | 1-249-433-11 |

**Applicable Serial Numbers:** All