

**SONY**

Car Stereo  
Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** XEC-500

**No.** 202

**Subject:** Part Number Correction: IC-901

**Date:** June 12, 1991

**Symptom:**  
(\*\*)

Please make the following correction on page 15 of your Service Manual:

**Solution:**

Reference	Incorrect		Correct	
	Description	Part Number	Description	Part Number
IC-901	NJM-2904S	8-759-981-74	M-5223L	8-759- <del>632-94</del>

Pre-Amp/Signal Processor  
CSA-14

Reference: FPR-M1194

PRINTED IN U.S.A.  
CSA-14591-9