

**SONY**

**Car Stereo  
Service Bulletin**

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** General

**No.** 203

**Subject:** Cleaning Liquid

**Date:** June 20, 1991

**Symptom:**  
(\*\*)

The recommended cleaning liquid for guides, capstan shafts and magnetic heads, part number 9-919-573-00, is no longer available.

**Solution:**

Please use either of the following replacement brands:

Product Name	Manufacturer	Catalog Number
Head Cleaner	Chemtronics	C1620L
Professional Cleaner Fluid	Realistic (Radio Shack)	44-1171A

General  
CSA-14

**Reference:**

PRINTED IN U.S.A.  
CSA-14691-1