

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-A30RF

No. 213

Subject: Part Number Addition: Plug Holder

Date: October 18, 1991


Symptom:
(**)

The part number for the remote commander plug holder was omitted from the Service Manual.

Solution:

Please add the following part number to page 23 of your Service Manual.

DESCRIPTION	PART NUMBER
Holder, Plug	2-358-580-01



CSA-14 CD Player