

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XK-8D

No. 224

Subject: Part Number Addition: Head Connector for HP-101

Date: January 20, 1992

Symptom:
(**)


The exploded view shown on page 20 of the Service Manual infers that the playback head (HP-101) and connector are stocked as a single assembly. However, this is not the case; the head and the connector must be ordered separately.

Solution:


Please add the following part number to your Service Manual.

DESCRIPTION	PART NUMBER
CONNECTOR, HEAD	3-372-153-01

INCORRECT



CORRECT



CSA-14 Cassette Player