

SONY

Car Stereo Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XES-C1

No. 226

Subject: Part Number Addition: Unilink Cable

Date: January 27, 1992


Symptom:
(**)

The part number for the Unilink Cable for XES-C1 is not listed in the Service Manual.

Solution:

Please add the following part number to your Service Manual:

DESCRIPTION	PART NUMBER
CABLE, UNILINK 8P (5.5M)	1-590-519-21



Compact Disc
CSA-14