

**SONY.**

Car Stereo  
Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** XK-8D

**No.** 232

**Subject:** Part Number Additions For Service Manual  
Supplement #1: Main MCB, Microcomputer MCB,  
Head AMP MCB, Power Supply MCB, Dolby MCB

**Date:** March 20, 1992

**Symptom:**  
(\*\*)

Part numbers for the Main MCB, Microcomputer MCB, Head AMP MCB,  
Power Supply MCB, and Dolby MCB are missing from the Service Manual Supplement #1.

**Solution:** Please add the following part numbers to Supplement #1 of the XK-8D Service Manual:

REFERENCE	DESCRIPTION	PART NUMBER
901	PC BOARD ASSY; MAIN	A-3216-291-B
902	MOUNTED PCB, MICROCOMPUTER	A-3216-293-B
903	MCB, HEAD AMP (SAME AS ORIGINAL)	A-3216-296-A
904	MCB, POWER SUPPLY	A-3216-321-B
905	MOUNTED PCB, DOLBY	A-3213-671-B

CSA-14  
Tape Player