

**SONY**

# Car Stereo Service Bulletin

Sony Service Company - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** XTC-100

**No.264**


**Subject:** Part Number Correction: Keyswitches S-800 to S-822 **Date:** October 30, 1992

**Symptom:**  
(\*\*)

The part number shown in the Service Manual for keyswitches S-800 to S-822 is incorrect.

**Solution:** Please make the following correction to your Service Manual:

REF.	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
S-800 TO S-822	SWITCH, KEYBOARD	1-572-655-11	1-572- <del>768</del> -11



Reference: FPR N2088

PRINTED IN U.S.A.  
CSA-141092-3

CSA-14 Tuner/Tape Deck