

SONY

Car Stereo Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: RM-X2

No. 265

Subject: Part Number Addition: CPU IC-305

Date: October 30, 1992

Symptom:
(**)

The part number for CPU IC-305 is missing from the Service Manual.

Solution:

Two different CPU's were used in the RM-X2. Order the part according to the type-number printed on the defective IC.

REFERENCE	DESCRIPTION	PART NUMBER
305	IC, μ PD75106G-543-1B	8-759-142-18
305	IC, μ PD75106G-532-1B	8-759-142-02

