

**SONY**

Car Stereo  
Service Bulletin

Sony Service Company Technical Services  
A Division of Sony Corporation of America  
Sony Drive Park Ridge, New Jersey 07656

**Model:** CDX-4040; EXCD-40

**No. 272**

**Subject:** Description & Part Number Correction -  
Reference No. R-712, Resistor, Mtl. Glaze, 4.7M


**Date:** December 30, 1992

**Symptom:**  
(\*\*)

The description and part number listed on page 47 of the original Service Manual for Ref # R-712, Resistor, Mtl. Glaze, 4.7M, is incorrect. The information in the newer service manual (part number 9-956-831-12) is correct.

**Solution:** Please note the correct description and part number as shown below.

REF	DESCRIPTION		PART NUMBER	
	INCORRECT	CORRECT	INCORRECT	CORRECT
R-712	RESISTOR, MTL GLAZE, 4.7M	RESISTOR, MTL GLAZE, 4.7K	1-216-286-00	1-216-214-00



CSA-14 CD Player

