

SONY

**Car Stereo
Service Bulletin**

Sony Service Company Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-U300RF

No. 275

Subject: Description & Part Number Correction -
Reference No. 58, Cord W/ Connector; addition
of power cable part number.



Date: February 26, 1993

Symptom:
(**)

The description and part number listed on page 22 of the Service Manual for Ref # 58, cord w/ connector, is incorrect. Also, the part number for the power cable was not shown in the Service Manual.

Solution: Please note the correct descriptions and part numbers as shown below.

REF	DESCRIPTION		PART NUMBER	
	INCORRECT	CORRECT	INCORRECT	CORRECT
58	CORD W/ CONNECTOR	CORD W/ CONNECTOR, DISPLAY	1-590-280-41	1-590-279-11
-	-	CORD W/ CONNECTOR, POWER	-	1-590-280-41



CSA-14 CD Player