

SONY

Car Stereo Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: EVX-S8

No. 277

Subject: Part Number Addition -
Audio/Video Cable


Date: March 31, 1993

Symptom:
(**)

The EVX-S8 car videocassette player is not packaged with an audio/video cable for connecting to a monitor and amplifier.

Solution: Please add the following part number to the Service Manual.

REF	DESCRIPTION	PART NUMBER
-	CABLE, AUDIO/VIDEO	T-9985-521-1



CSA-14 Miscellaneous

Reference: FPR-O1055
Autoflagged - NO



PRINTED IN U.S.A.
CSA-14393-2