

SONY.

**Car Stereo
Service Bulletin**

CSA-14

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: GEN-CAR

No. 287R1

Subject: Standardized Power Cords Available For
Troubleshooting.

Date: August 22, 1995

Symptom:

(**) The following cords with connectors, which have been designed as standardized power cords, are available for troubleshooting Sony car stereo products. Refer to the service manuals for pin layouts and connections. Also, note that the connectors do not contain fuses, as the current rating varies from model to model.

Solution: Order the power cords from the National Parts Center as follows.

This revision is being issued to add five additional power cords which have become available subsequent to the original bulletin.

Previous Cords	
New Cords	
Connector Type	Part Number
3 Pin Connector	J-2502-003-1
5 Pin Connector	J-2502-003-2
7 Pin Connector	J-2502-003-3
9 Pin Connector	J-2502-003-4
11 Pin Connector	J-2502-003-5
13 Pin Connector	J-2502-003-6
15 Pin Connector	J-2502-003-7
17 Pin Connector	J-2502-003-8
15 Pin Connector	J-2502-013-1
18 Pin Connector	J-2502-013-2

