

**SONY** Car Stereo  
**Service Bulletin**

**CSA-14**

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** XR-U220/U330

**No. 300**

**Subject:** Availability Of Extension Cable.

**Date:** October 19, 1993


**Symptom:**  
(\*\*)

Troubleshooting and repair may be difficult if an extension cable is not used.

**Solution:** An extension cable may be ordered from the National Parts Center as follows:

REF	DESCRIPTION	PART NUMBER
	EXTENSION CABLE, MAIN BOARD TO AMP BOARD	J-2502-005-3

Please note that the red wire of the cable should connect pin 1 (TEL MUTE) of CNP901 with pin 1 (TEL MUTE) of CNP101.



Reference: Technical News ME-93007  
Autoflagged - NO



PRINTED IN USA  
CSA-141093-4