

**SONY.**

**Car Stereo  
Service Bulletin**

**CSA-14**

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** GEN-CAR

**No.** 312

**Subject:** Part Number Addition: Eject Cam

**Date:** March 4, 1994

**Symptom:**

(\*\*)

The eject cam for the mechanical decks listed below has previously not been available.


**Solution:**

The eject cam can now be ordered through the National Parts Center.

REF	DESCRIPTION	PART NUMBER
-	EJECT CAM	3-375-382-01

Applicable mechanical decks (mechanical deck type numbers can be found on the front cover of the service manuals):

MG-36AS-32      MG-36SHJ-32      MG-36SZ1-32  
MG-36AS1-32    MG-36SV-32      MG-36SZ3-32  
MG-36AS2-32    MG-36SV2-32     MG-36SZ4-32  
MG-36ASH-32



Reference: SOCAN CS-256  
Autoflagged - NO



PRINTED IN USA  
CSA-14294-5