

SONY

Car Stereo Service Bulletin

CSA-14

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-130/150

No. 327

Subject: Part Number Correction - Reference No. 58, Panel, Front

Date: July 25, 1994


Symptom:
(**)

The part number listed on page 48 of the Service Manual for Ref # 58, Panel, Front, is incorrect.

Solution:

Please note the correct part number as shown below.

REF	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
58	PANEL, FRONT (XR-130)	3-389-041-51	3-389-041-53
58	PANEL, FRONT (XR-150)	3-389-041-41	3-389-041-43



Reference: FPR-P1797
Autoflagged - NO

PRINTED IN USA