

SONY.

Car Stereo Service Bulletin

CSA-14

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-A55

No. 328

Subject: Part Number Correction - Reference No. VR451,
Resistor, Variable (W/Switch)

Date: July 25, 1994

Symptom:
(**)

The part number listed on page 28 of the Service Manual for Ref # VR451, Resistor, Variable (W/Switch), is incorrect.

Solution:

Please note the correct part number as shown below.

REF	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
VR451	RESISTOR, VARIABLE W/SWITCH	1-238-874-11	1-241-982-11

