

# Car Stereo Service Bulletin

**CSA-14**

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** GEN-CAR

**No.** 340

**Subject:** Extension Cables For Servicing Removable  
Faceplates

**Date:** November 16, 1994

**Symptom:**

(\*\*)

It may be difficult to repair the removable faceplates without using an extension cable which allows it to be electrically connected to the main unit.

**Solution:** The extension cables shown below are available from the National Parts Center.

| MODEL   | PART NUMBER  |
|---|--------------|
| XR-U220/U330  | J-2502-009-0 |
| XR-U500/U700/U800   | J-2502-009-2 |
| XR-U550/U660  | J-2502-009-3 |
| EXR-22; XR4400/5500/5600/U110   | J-2502-009-4 |
| XR-5450/5550  | J-2502-009-5 |
| CDX-5060/5260/5460/U6260  | J-2502-009-7 |
| CDX-5070/5270/5470/600DSP;<br>EXR-18;<br>XR-340/430/3200/3320/<br>4420/5620/C210/C410 | J-2502-009-8 |





Filename: CAR0340.SB  
Directory: J:\SBDOC\NOV94  
Template: C:\WINWORD\S\_BULL.DOT  
Title:  
Subject:  
Author: Hoyt Wing Lee  
Keywords:  
Comments:  
Creation Date: 11/16/94 2:03 PM  
Revision Number: 2  
Last Saved On: 11/16/94 2:03 PM  
Last Saved By: Hoyt Wing Lee  
Total Editing Time: 0 Minutes  
Last Printed On: 04/01/96 10:01 AM  
As of Last Complete Printing  
Number of Pages: 2  
Number of Words: 161 (approx.)  
Number of Characters: 919 (approx.)