

Car Stereo Service Bulletin

CSA-14

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: CDX-45RF/65RF/U303RF;
EXCD-1RF

No. 350

Subject: Part Number Correction: Q503

Date: February 1, 1995

Symptom:

(**)

The part number shown in the service manuals and supplements for Q503 is incorrect.

Solution:

Please make the following correction to the manuals and supplements.

REF	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
Q503	TRANSISTOR, 2SD1417	8-729-240-10	8-729-204-10



