

**SONY**

Hi-Fi Products  
Service Bulletin

**Sony Service Company** - Technical Services  
A Division of Sony Corporation of America  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** CDP-950/307ESD/707ESD

**No.** 27

**Subject:** Custom Filed Memory Is Lost

**Date:** July 29, 1988

**Symptom:**  
(322)

If the following capacitors or connectors are removed during servicing, the custom filed memory will be lost.

**Solution:**

Model	Capacitor Ref. No.	Connector Number
CDP-950	C904	---
CDP-307ESD	C904	---
CDP-507ESD	C901	---
CDP-707ESD	C873	CNJ718

Compact Disc

CSA-13