

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: STR-AV950

No. 33

Subject: Part Number Missing - C810/860


Date: September 19, 1988

Symptom:
(**)

The power supply filter capacitors on the +56V line (C810/860) are not listed in the parts list. Please note the part number listed below:

Solution:

Ref. No.	Description	Part Number
C810/860	Capacitor, Electrolytic 15000 μ F/71V	1-125-430-11



Receiver
CSA-13

Reference: KCP

PRINTED IN U.S.A.
CSA-13888-4