

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: FH-11W

No. 36

Subject: Part Number Correction -
Rec/Playback Head

Date: September 19, 1988

Symptom:
(**)

The part number listed in the service manual (page TC-35) for the Rec/Playback heads for Decks A and B is incorrect. Please note the correct part number listed below:

Solution:

Ref. No.	Description	Part Number	
		Incorrect	Correct
HP901 (Deck A)	Rec/Playback Head	8-825-507-01	1-543-354-11
HRP901 (Deck B)	Type PP271-3602		

Compact Systems

CSA-13