

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: TC-K700ES/K555ES/K666ES/K777ES

No. 38

Subject: Rec/Playback Head

Date: September 19, 1988

Symptom:
(**)

Solution: Replace the Rec/Playback Head with the new part listed below:

Description	Part Number	
	Former	New
Rec/Playback Head RPA230-3602	8-825-500-32	8-825- <u>770-51</u>

CSA-13
Tape Deck

Reference: T/N TCO-870416

PRINTED IN U.S.A.
CSA-13888-9