

SONY

Hi-Fi Products
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: D-15

No. 39

Subject: Portable Disc Player

Date: October 10, 1988


Symptom:
(51)

PCB shorts to the chassis.

Solution:

Please add an insulating sheet to the servo PCB as shown.

Description	Part Number
Servo PCB Insulating Sheet	4-926-105-01



Portable Compact Disc
CSA-13

Reference: Intermittent/No Sound

PRINTED IN U.S.A.
CSA-11988-1